

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Problem Image Mailbox.**


FIG 4



- block = I
- $\frac{1}{4}$ " plate steel
- $\frac{1}{2}$ " post board
- $3"$  Mc Channer
- $2\frac{1}{2}$ " angle iron
- rubber seal

Berry door cut away

FTG 2.



| FIG 5 ]







PLATE  
POLY FASTENER cut Acrylic





I Block = 3"

Fig. 6  
I-Slot U-Gate w/  
20°





20

Fig. 7

60

Fig. 8

